EARLE'S TRUCK REPAIR, INC

PO BOX 14

59 NORTH CAMPBELL RD. CENTER RUTLAND VT 05736

802-773-9198

page 1

Estimate #41064

TOWN OF CASTLETON 263 RT 30 NORTH BOMOSEEN VT 05732

Day Phone 802-468-5319

Fax Number 802-468-5482

-fold here -

Vehicle : 2013 International Workstar 7600 6, 13.0L (793 CID)

VIN : 1HTGSSJT5DJ257316 Last Mileage : 47549

Fleet # : TRK 12

Created : 12/12/2023 10:01:58 AM Odometer Out : 50186

Contact : EVAN CHALMERS

Labor/Notes

 Qty
 Code/Tech*
 Description
 Unit Price
 Price

 1
 SHOP LABOR - FLEET
 \$5,800.00
 \$5,800.00

CHECKED TRUCK OVER VT STATE INSPECTION AND THEY BROUGHT A LIST.

DUMP PISTON LEAKING, WILL REMOVE AND HAVE CHECKED TO SEE OF OKAY TO REBUILD. IF NOT WE WILL REPLACE.

NEEDS FRONT KING PINS REPLACED.

REPAIR POWER STEERING LEAK, NEEDS FITTINGS REPLACED.

REPLACE STEER AXLE BRAKE CAN, RELAY VALVE, RIGHT REAR BRAKE CAN.

REPAIR AIR LEAK ON FIRE WALL. NEEDS AIR VALVE REPLACED THAT CONTROLS EXH BRAKE FROM TURBO.

NEEDS EXHAUST CLAMPS REPLACED

NEEDS DRIVERS SIDE DRAG LINK,

REPLACE SUSPENSION TOP HATS.

REPAIR ALL LIGHTS, REVERSE, MARKERS, STROBES. REPLACE WIPER BLADES.

SERVICE AIR DRYER.

ENGINE LIGHT, PUT ON COMPUTER. ALL CODES ARE FOR EGR.

DIAGNOSE AND REPLACE EGR VALVE

REPLACE PTO UJOINTS.

PULL ALL REAR WHEELS AND REPLACE SCAMS AND BUSHINGS.

Parts					
Qty Co	ode/Tech*	Description	Condition	Unit Price	Price
2	<u> </u>	WHELEN 5G SERIES AMBER STROBE		\$109.08	\$218.16
2		FREIGHT CHARGES - UNKNOWN AT THIS TIME		\$0.00	\$0.00
2		SPOT LIGHT W/ SPADE TERMINALS		\$19.35	\$38.70
1		AD-SP DRYER FILTER		\$66.53	\$66.53
1		TYPE 24 SERVICE BRAKE CHAMBER-LS WELDED CLEVIS		\$44.47	\$44.47
1		POWER STEERING PUMP FITTING		\$39.98	\$39.98
1		POWER STEERING PUMP FITTING		\$59.83	\$59.83
1		POWER STEERING PUMP O-RING		\$8.33	\$8.33
1		R7 MODULATING RELAY VALVE		\$172.52	\$172.52